

List of materials/equipment/supplies needed to comply with Asbestos and Lead SWPs

- 6 mil plastic
- HEPA vacuum
- Regulated Area signs/ Waste signs
- Framing materials (duct tape, PVC pipes, other)
- Caution tape
- Glovebags
- Personal protective equipment (respirators, disposable work clothing/booties, eye protection)
- Air monitoring equipment (pump, sampling cartridges, calibrator)
- Bulk sampling materials (sampling containers, spray misters, knife, cutter, borer, drill, sponges, shaving cream, caulking, labels)
- Wipe sample collection media
- Contract with accredited laboratory/Chain of Custody Forms